

Tail Shaft Spacer

Triton ML MN

Is your Manual ML/MN Triton (06-on) suffering from significant driveline vibration following a suspension lift? This is most likely due to the fact that the Manual ML/MN Triton has a two piece drive shaft with centre bearing. Your mate in the Auto ML Triton, with the same lift, will not have the same issues because the Auto versions have a single piece drive shaft. The Roadsafe 13.25mm Diff Spacer is fitted between the rear drive drive shaft and the diff, lowering the bearing by 5-8mm, and compensates for the absence of a slip joint in the drive shaft, prolonging the life of the Centre Bearing. It is not designed to fix vibration issues.



TSSTRI

Part Number TSSTRI
Description Triton Tail Shaft Spacer
Barcode 9319478603714

Now Available



VIC - Phone 1300 651 551 Fax 1300 651 451
QLD - Phone 1300 559 086 Fax 1300 559 842