

TAP107

DECEMBER 18

Ball Stud Separation

Some Sway Bar Links are handed, meaning they have side specific fitment. It is imperative that the links are fitted to the correct side of the vehicle, in the correct orientation. Incorrect installation can lead to the ball studs separating from the housing. When you see this kind of failure it has been brought about by the incorrect selection or installation of the component, and is not a manufacturing fault. This type of failure is readily seen with STB8822/23 (VE Commodore) Sway Bar Links.



STB8822/23 sway bar links (VE Commodore) fitted to incorrect side of vehicle results in the ball studs separating from the housing.

Manufacturers Names used for reference purposes only.