

UCA3956R - FORD RANGER PK/PJ & MAZDA BT-50 2008-2012

This Technical bulletin is provided as a general reminder to double check during install that all bolts are assembled correctly with relevant split washer, torque and Loctite as required by standard mechanical practices or as instructed in the manufacturers workshop manual. Please ensure the 3 bolts that retain the Ball joint to the arm are secure and torqued correctly as per the Manufacturers specifications.



*Manufacturers Names used for reference purposes only.