

November 2013 RAP316A

Top Strut Mount Toyota Prado 95 Series

Now available from Roadsafe is a replacement Top Strut Mount for the Prado 95 Series. It is a common issue on standard Prado 95 Series strut top mounts for the rubber bushing to wear out. This is especially common on lifted vehicles and vehicles that see a general amount of offroad use. Bushing wear results in the strut shaft wearing through the strut top plate leading to damage to the strut top in addition to the strut shaft, resulting in costly repairs.

Heavy Duty Rubber Bushing
Extended Studs
Complete with stud nuts

Replaces 48609-35030

Part Number S0485R
Description Prado 95 Strut Mount
Barcode 9319478607842

Now Available



VIC - Phone 1300 651 551 Fax 1300 651 451 QLD - Phone 1300 559 086 Fax 1300 559 842

E.& O.E.