




BJ3881 now available Greasable Hilux 05-on Upper Ball Joint

Standard
Replacement

Now
Available
Greasable



BJ3881HD

Part Number **BJ3881HD**
Description **Hilux 05-on Upper**
Barcode **9319478607941**

Also Available

25mm Extended Ball Joint

If you have a lifted 05-on Hilux and during articulation you hear a clunk during full articulation, it might be the Front Upper Control Arm making contact with the Coil. Roadsafe have a 25mm extended Upper Ball Joint that fits to the Upper Control Arm, to space the arm far enough to avoid the factory upper arm contacting the coil on full droop. As an added bonus, it also provides an extra inch of downward travel, plus improves caster.



Now Available



VIC - Phone 1300 651 551 Fax 1300 651 451
QLD - Phone 1300 559 086 Fax 1300 559 842

