

Top Strut Mount

Colorado / D-Max 04-08

Now available from Roadsafe is a replacement Top Strut Mount for the Colorado / D-Max 04-08. It is a common issue on standard Colorado & D-Max strut top mounts for the rubber bushing to wear out. This is especially common on lifted vehicles and vehicles that see a general amount of offroad use. Bushing wear results in the strut shaft wearing through the strut top plate leading to damage to the strut top in addition to the strut shaft, resulting in costly repairs.

- Heavy Duty Rubber Bushing
- Complete with stud nuts

S0493R

Part Number S0493R

Description Colorado/DMax Strut Mount

Barcode 9319478620285

Now Available



VIC - Phone 1300 651 551 Fax 1300 651 451
QLD - Phone 1300 559 086 Fax 1300 559 842