



Landcruiser 78 & 79 Series Track & Relay Rods Upgraded Sizing

- Upgraded 30-34mm OD Tube
- Upgraded 5.7-6.5mm Wall Thickness
- Complete with Tie Rod Ends
- Heavy Duty Greasable Ends
- Lock Nut instead of External Clamp

When purchasing Genuine you must buy the rod separate to the ends. Roadsafes offer you a complete solution in the one purchase!

Check out the Comparison...



| Part Number | Application | Location | Genuine Rod Length (mm) | Rod OD (mm) | Wall Thickness (mm) | Ends Included | Barcode |
|-------------|--------------------------------|-----------|-------------------------|-------------|---------------------|---------------|---------------|
| TR4530 | LANDCRUISER 78/79 SERIES | TRACK ROD | 1020 | 34 | 6.5 | TE995/997 | 9319478506244 |
| TR4610 | LANDCRUISER 78/79 SERIES | RELAY ROD | 840 | 30 | 5.7 | TE2754/2755 | 9319478506299 |
| TR4563 | LANDCRUISER 76/78/79 V8 SERIES | TRACK ROD | 1105 | 34 | 6.5 | TE995/997 | 9319478535985 |
| TR4554 | LANDCRUISER 76/78/79 V8 SERIES | RELAY ROD | 920 | 30 | 5.7 | TE2754/2755 | 9319478535978 |

Available Now!

E. & O.E.

VIC - Phone 1300 651 551 Fax 1300 651 451
QLD - Phone 1300 559 086 Fax 1300 559 842

