

Extended Ball Joint Hilux 05-on Upper

If you have a lifted 05-on Hilux and during articulation you hear a clunk during full articulation, it might be the Front Upper Control Arm making contact with the Coil. Roadsafe have a 25mm extended Upper Ball Joint that fits to the Upper Control Arm, to space the arm far enough to avoid the factory upper arm contacting the coil on full droop. As an added bonus, it also provides an extra inch of downward travel, plus improves caster.



BJ4081

Part Number BJ4081
Description Hilux Upper
Barcode 9319478596399

Ask your Representative for more information

Now Available



VIC - Phone 1300 651 551 Fax 1300 651 451
QLD - Phone 1300 559 086 Fax 1300 559 842