

RAP512A - July 2018

EXTENDED UPPER BALL JOINT

PX RANGER | EVEREST | BT50

GREASABLE DESIGN



BJ4086

Part Number BJ4086
Extended Upper Ball Joint
Ranger PX/BT50 (Gen 2)
Barcode 9319478647640
RRP* \$75.00

On lifted vehicles, there is often complaints of a 'clunking noise' heard at full articulation. This is often caused by the front upper control arm making contact with the coil. Roadsafe extended upper ball joints are designed to space the factory arm far enough to avoid the factory upper arm hitting the coil on full droop. As an added bonus, they also provide an extra 20mm of downward travel, plus improve caster. Based on the BJ3957 (standard body size) ball joint, the Roadsafe 20mm Extended Upper Ball Joint to suit PX Ranger/BT50 is greasable and has been redesigned from standard to include a Retaining Circlip.

Extended upper ball joints should not be fitted with aftermarket arms designed to include increased camber/caster.

**CHECK OUT THE ROADSsafe
4WD EDITION 4 CATALOGUE FOR
FURTHER EXTENDED UPPER
BALL JOINT FITMENTS.**



*Pricing listed was correct at time of product bulletin preparation