



DECEMBER 18  
TAP110

## FORD PX3 RANGER & EVEREST 06/2018-ON TOW POINT INSTALLATION - RP-RAN02

Applicable to vehicles manufactured post JUNE 2018.

A stiffening plate installed inside the chassis rail affects access to one hole used in the fitment of RP-RAN02 (Refer Image). Using a step drill enlarge this hole to allow fitment of the supplied hardware. The spacer pictured will require modification to clear the new weld not present on previous vehicles.

The nut plate will sit behind the stiffening plate, with the bolt passing through.



\*All existing fitment details apply with regards to bull bar compatibility.  
Manufacturers Names used for reference purposes only.