

# Top Strut Mount Toyota Hilux 05-on

Now available from Roadsafe is a replacement Top Strut Mount for the Hilux IFS 150 Series. It is a common issue on standard Hilux strut top mounts for the rubber bushing to wear out. This is especially common on lifted vehicles and vehicles that see a general amount of offroad use. Bushing wear results in the strut shaft wearing through the strut top plate leading to damage to the strut top in addition to the strut shaft, resulting in costly repairs. Roadsafe have redesigned the standard mount to include:

- Heavy Duty Washers
- Heavy Duty Rubber Bushing
- Extended Studs
- Complete with stud nuts



## S0486R

Replaces 48609-60100

Part Number S0486R  
Description Hilux Strut Mount  
Barcode 9319478593053

# Now Available



VIC - Phone 1300 651 551 Fax 1300 651 451  
QLD - Phone 1300 559 086 Fax 1300 559 842