

VEHICLE Toyota Landcruiser 76 / 78 / 79 Series

PRODUCT Diff Lock Actuator Guard

PRODUCT CODE SB059

BARCODE 9319478661684

The diff lock actuator is located in a vulnerable position which can be subject to stone and other damage if impacted by unforgiving terrain when off road. This Toyota component is a genuine-only replacement part – considerably more than the cost of a guard!

Manufactured locally in Australia from 304 stainless steel to ensure a lifetime of corrosion resistance. Easy install with basic hand tools.

DESIGNED & MANUFACTURED IN AUSTRALIA!

- 3mm 304 stainless steel
- Australian made
- Reinforce and strengthen the OE mount
- CNC laser cut & folded
- Retail packaging

