



Toyota Yaris 03-on Ball Joints & Arms

BJ9135

RH Lower Control Arm

Replaces Genuine 48068-59135



BJ9136

LH Lower Control Arm

Replaces Genuine 48069-59125



BJ4192

**Lower Ball Joint Only
Not Serviceable
Genuine**



Part Number: BJ4192
Bar Code: 9319478525313
Suit: **Yaris Lower Ball Joint**

Part Number: BJ9135+ARM
Bar Code: 9319478525764
Suit: **Yaris RH Lower C/Arm**

Part Number: BJ9136+ARM
Bar Code: 9319478525788
Suit: **Yaris LH Lower C/Arm**

Available Now!

E.&O.E.

VIC - Phone 1300 651 551 Fax 1300 651 451
QLD - Phone 1300 559 086 Fax 1300 559 842

