

# Landcruiser (& Lexus)

## Sway Bar Links

### Standard Replacements

Part No.	Replaces Genuine No.	Model	Year	Location
STB7843	48820-60040	FJ80, HDJ80, HZJ80	91-97	Front
STB7859	48802-60030	FJ80, HDJ81, HZJ81	91-92 & 96-97	Rear
STB7856	48820-60031	UZJ100 & Lexus LX470	98-04	Front
STB7901	48802-60070	UZJ100 & Lexus LX470	1998	Rear
STB7857	48802-60090	UZJ100 & Lexus LX470	99-04	Rear



Sway Bar Link Extensions also Available.  
See STBEXT001, SRBEXT002, STBEXT005.

# Available Now!

E. & O.E.

VIC - Phone 1300 651 551 Fax 1300 651 451  
QLD - Phone 1300 559 086 Fax 1300 559 842

